



FIRE PREVENTION BUREAU

MONTHLY REPORT

AUGUST 2014

New Businesses

- 5403 Patton #203 — Innovative Plumbing Inc.
- 4714 Main — Green Collection Inc.
- 2757 Maple — Baby Love It
- 4995 Varsity #B — Ultimate Motorsports
- 1998 Ohio #100 — Gateway Cable Inc.

New Construction Projects

- 5730 College — BU Business Building
- 5515 Main — Hardees
- Ogden and Karnes — Arbor Place of Lisle
- 4314 Lincoln — New retail building
- St. Joan of Arc — Interior renovations
- 2799 Maple — Building renovation
- 2200 Western #100 — Interior remodel
- 801 Warrenville, 4th Floor — Interior demo
- 2300 Cabot #425 — Interior remodel
- 2200 Maple, 4th Floor — Interior remodel
- 2350 Maple — Build restrooms/concessions
- 2525 Cabot #105 — Interior remodel
- 1946 University — Bring existing space up to code
- 2901 Ogden — Interior remodeling

Points of Interest

Smoke detection is required at fire alarm control units that notify occupants and responders of a fire. In rooms that contain total smoke detection coverage, additional detectors at the control unit are not required. Where total detection is not provided only one detector is required at the control unit, even if the room would require additional detectors, but it must be located according to standard location rules. Many installers incorrectly interpret the phrase ‘at the panel’ literally and improperly install it on a wall above the panel, as is found in the photo on the right; this detector is wall mounted about 15 feet below the ceiling rather than on the ceiling.

Code Enforcement Activities

<i>Activity</i>	<i>Current</i>	<i>YTD</i>
Inspections (Existing)	282	1902
Inspections (New)	25	174
Plan Reviews	26	249
Knox Box Updates	98	839
Hazard Investigations	41	290
Code Meetings	35	246
System Follow Ups	119	763

Public Education Activities

<i>Activity</i>	<i>Current</i>	<i>YTD</i>
Fire Safety Talk or Demo	3	29
Fire Station Tour		22
Fire Extinguisher Training		0
Fire Drill	3	18
Miscellaneous Public Education	2	6

