

FIRE PREVENTION BUREAU

MONTHLY REPORT

May 2015

New Businesses

1001 Warrenville #175 — Title Settlement Services

1001 Warrenville #110 — C.F. Funding Corp

4225 Naper #155 — Armour-Eckrich Meats LLC

4724 Main— Alliance Health Spa

1111 Burlington #104 — Network Cabling

Construction Projects

5730 College — BU Business Building

4795 Karnes — Arbor Place of Lisle

4314 Lincoln — New retail building

8099 Janes — Woodridge Horizon Senior Living

8201 Janes — Woodridge Park District ARC

4100 RT 53 — Morton Arboretum South Farm

4100 RT 53 — Ginko Restaurant remodel

1036 Maple — Interior remodel

750 Warrenville, 4th Floor — Interior demolition

550 Warrenville #100A — Interior remodel

2250 Maple — Remodel gym entrance

2901 Ogden — Restaurant remodel

Points of Interest

Sidewall sprinklers shall not be spaced closer than six feet on center unless protected by baffles (right) to prevent cold soldering. Baffles need to be of a solid material that will stay in place while the sprinkler head is activating. The minimum size is six inches by eight inches. The top of the baffle shall extend between two and three inches above the deflector and the bottom of the baffle shall extend downward at least even with the deflector.

Code Enforcement Activities

Activity	Current	YTD
Inspections (Existing)	139	806
Inspections (New)	29	143
Plan Reviews	31	197
Knox Box Updates	73	369
Hazard Investigations	34	179
Code Meetings	27	112
System Follow Ups	78	586

Public Education Activities

Activity	Current	YTD
Fire Safety Talk or Demo	0	3
Fire Station Tour	2	7
Fire Extinguisher Training	0	2
Fire Drill	0	0
Miscellaneous Public Education	3	5

