



FIRE PREVENTION BUREAU

MONTHLY REPORT

MAY 2016

New Businesses

- 1001 Warrenville #210 — Spyratos
- 801 Warrenville #560 — J Tracks
- 2150 Western — Sunrise Transportation

Construction Projects

- 1010 Burlington/4755 Main — Main Street Village
- 8099 Janes — Woodridge Horizon Senior Living
- 8201 Janes — Woodridge Park District ARC
- 4100 RT 53 — Morton Arboretum South Farm
- 1650 Maple — Restaurant Remodel
- 1955 University — Sprinkler System Upgrade
- 6690 RT 53 — Interior Alterations
- 750 Warrenville — Interior Alterations
- 4324 Yackley — Interior Remodel
- 2029 Ogden — Kitchen Suppression System Install
- 2200 Maple — Interior Remodel

Points of Interest

Cover Plates are required to be part of the listed sprinkler head assembly, unpainted, and able to freely dislodge from the sprinkler head to allow the spray pattern to develop. In the photo on the right the cover plate had fallen off and the maintenance worker 'repaired' it by bending the metal on the head around the cover plate to hold it in place. If exposed to heat this cover plate will not fall off and the head will be inoperable.

Code Enforcement Activities

<i>Activity</i>	<i>Current</i>	<i>YTD</i>
Inspections (Existing)	179	1002
Inspections (New)	30	131
Plan Reviews	22	119
Knox Box Updates	43	373
Hazard Investigations	44	184
Code Meetings	20	121
System Follow Ups	145	546

Public Education Activities

<i>Activity</i>	<i>Current</i>	<i>YTD</i>
Fire Safety Talk or Demo	4	8
Fire Station Tour	4	10
Fire Extinguisher Training	0	0
Fire Drill	0	0
Miscellaneous Public Education	1	4

