



FIRE PREVENTION BUREAU

MONTHLY REPORT

OCTOBER 2015

New Businesses

- 906 Lacey #209 — The Good Shepherd Home Care
- 701 Warrenville #110 — CDM Smith
- 4513 Lincoln #210 — Qualified Pension Professionals
- 4699 Auvergne #13 — Shatter Brain

Construction Projects

- 1010 Burlington/4755 Main — Main Street Village
- 8099 Janes — Woodridge Horizon Senior Living
- 8201 Janes — Woodridge Park District ARC
- 4100 RT 53 — Morton Arboretum South Farm
- 22W070 Butterfield — Mobil Garage addition
- 1800 Robin — Critical equipment relocation
- 2500 Cabot — Lobby Remodel
- 2801 Ogden #3 — Lobby Remodel
- 2100 Western #100 & 150 — Interior Remodel
- 6440 Main #220 — Interior Remodel
- 801 Warrenville #300 — Interior Remodel
- 4513 Western — Lobby Remodel

Points of Interest

Smoke detectors (right), when mounted on the ceiling, shall be directly on the ceiling, with the exception of certain cases where exposed solid structural members are used. This detector was incorrectly installed on the bottom of an open web bar joist. Heat/smoke would travel up past the detector and collect at the ceiling level, delaying activation. The contractor who performed this installation also exceeded the manufacturer's listed spacing requirements for the detectors. Spacing is typically 30 feet (meaning 30 feet between detectors and 15 feet from a side wall).

Code Enforcement Activities

| <i>Activity</i> | <i>Current</i> | <i>YTD</i> |
|------------------------|----------------|------------|
| Inspections (Existing) | 247 | 1655 |
| Inspections (New) | 26 | 270 |
| Plan Reviews | 38 | 378 |
| Knox Box Updates | 114 | 739 |
| Hazard Investigations | 31 | 341 |
| Code Meetings | 21 | 210 |
| System Follow Ups | 56 | 933 |

Public Education Activities

| <i>Activity</i> | <i>Current</i> | <i>YTD</i> |
|--------------------------------|----------------|------------|
| Fire Safety Talk or Demo | 6 | 17 |
| Fire Station Tour | 0 | 9 |
| Fire Extinguisher Training | 0 | 4 |
| Fire Drill | 22 | 34 |
| Miscellaneous Public Education | 5 | 19 |

