

#### FIRE PREVENTION BUREAU

#### **MONTHLY REPORT**

#### **AUGUST 2015**

### New Businesses

2300 Cabot #315 — NCI

2731 Maple — Art Room

6440 College — Green Healthy Café

650 Warrenville, 4th Floor — Optum

2733 Maple — Max Martial Arts

## Construction Projects

5730 College — BU Business Building

8099 Janes — Woodridge Horizon Senior Living

8201 Janes — Woodridge Park District ARC

4100 RT 53 — Morton Arboretum South Farm

2901 Ogden — Restaurant remodel

2222 Wellington — Fitness Center expansion

2310 75th Street — McDonalds site improvements

22W070 Butterfield — Mobil Garage addition

1800 Robin — Critical equipment relocation

4951 Indiana #100 and #600 — Interior remodel

1936 Univeristy — Interior remodel

2300 Cabot #550 — Interior remodel

## Points of Interest

Hydraulic Placards (pictured at right) are required by NFPA 14 to be posted at the Fire Department Connection. The number represents the pressure required at the connection to meet the design demand with 100psi residual. This placard is posted at 4795 Karns and the number boxed in at the lower right corner is the required pressure to achieve 1000gpm with 100psi residual at the most remote hose valve.

# Code Enforcement Activities

Activity	Current	YTD
Inspections (Existing)	144	1299
Inspections (New)	33	216
Plan Reviews	39	302
Knox Box Updates	82	586
Hazard Investigations	33	285
Code Meetings	18	165
System Follow Ups	108	787

### Public Education Activities

Activity	Current	YTD
Fire Safety Talk or Demo	1	9
Fire Station Tour	0	9
Fire Extinguisher Training	0	4
Fire Drill	9	10
Miscellaneous Public Education	1	13

